

COMMENT SECTION

Location for Vendor TD and KTD to input comments for current sample round.

1. Measurer 1 Fit Comments field is for Vendor TD comments.
2. Measurer 2 Fit Comments field is for Kohl's TD comments.

Fit Evaluation: 108143

Overview Attachments Change Tracking 12 More Actions...

Measurer 1 Fit Comments

Measurer 2 Fit Comments

MEASUREMENT SECTION

Location for input of current sample measurements.

1. Measurer 1 is for Vendor measurement
2. Measurer 2 is for Kohl's TD measurement
3. Delta field is the calculation from measurement to actual spec. Measurements that fall out of tolerance will be highlighted in red font.
4. **Measurer 1 Comments/Measurer 2 Comments:** Only use for short comments when needed. There is a limited number of characters that will show.

Details 5013378

Points of Measure							Sample Specification							
QA	P/S	Attachment	Code	POM Description	Tol(-)	Tol(+)	Spec	Measurer 1 Actual	Measurer1 Delta	Measurer 1 Comments	Measurer 2 Actual	Measurer 2 Delta	Measurer 2 Comments	Rev
	P		A122	MINIMUM HEAD STRETCH	0	0	25							
	P		A300	*LGTH HPS TO HEM- FRONT	-1/2	1/2	28 1/2	28 1/2	0					
			A151	FORWARD SHLDR SEAM @HPS-STRAIGHT	-1/8	1/8	1/2	1/2	0					
	P		A100	*NK WIDTH @ SEAM	-1/4	1/4	7 1/2	7 1/4	-1/4					
	S		A110	_FRT NK DROP @ SEAM	-1/8	1/8	4 1/2	4	-1/2					
	S		A120	_BK NK DROP @ SEAM	-1/8	1/8	7/8	7/8	0					
			A124	NK TRIM HEIGHT	-1/8	1/8	5/8	5/8	0					
	P		A250	_ACROSS SHOULDER	-3/8	3/8	17 3/4	17 3/4	0					
	S		A253	_ACROSS FRT/BK PLCMT FRM HPS	0	0	7							
	S		A254	_ACROSS FRT	-3/8	3/8	15 1/4	15 1/8	-1/8					

