

Wet Season Requirements

Wet Season:

- **Temp:** ≥ 28°C
- **RH:** ≥ 70%
- **Avg Monthly Rainfall:** ≥ 100mm

Other things to Note:

- All Materials can develop mold or experience corrosion during the wet season!
- We require desiccants for **all shipments during this season** based on the COP.
- For all Mold/ Moisture suppliers, us of the nominated matrix is required.

Questions? Reach out to pbtrimslablespackaging@kohls.com

AREA	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
Bangladesh												
Cambodia												
China, South												
China, East												
China, North												
Taiwan China												
Indonesia												
India												
Japan												
Korea												
Laos												
Malaysia												
Myanmar												
Pakistan												
Philippines												
Sri Lanka												
Thailand												
Vietnam												

- China, South: Guangdong, Fujian, Jiangxi, Hunan, Hubei, Guangxi, Hainan, Hong Kong
- China, East: Zhejiang, Shanghai, Jiangsu, Anhui, etc.
- China, North: Beijing, Tianjin, Shandong, Shanxi, Hebei, etc.